

**Sir Safety System S.p.A. Single-member company**  
Wholly-owned subsidiary of Sir Holding Srl  
Via dei Fornaciai, 9 - Santa Maria degli Angeli  
06081 Assisi - Perugia - Italy  
Tel.+39 075.8043737 (R.A.) - Fax +39 075.8048686

VAT Nr. IT 03359340548  
Viale Europa 74  
20090 Cusago Milano  
Tel. +39 02.90394575 (R.A.)  
Fax +39 02.90394441

**export@sirsafety.com**  
**www.sirsafety.com**

COMPANY WITH  
QUALITY SYSTEM  
CERTIFIED BY DNV GL  
= ISO 9001 =



|                          |                    |                      |
|--------------------------|--------------------|----------------------|
| <b>Name: Nevada Vest</b> | <b>Code: 30651</b> | <b>Nevada Series</b> |
|--------------------------|--------------------|----------------------|

### Description

Vest made in Evolution fabric, 65% polyester and 35% cotton, weight 240 g/ m², jointed double stitching with high resistance.

Features: zipper closure, two chest pockets with flap and pen holder.

Bicolor model: Turquoise 21 – flaps Navy Blue18.

Mechanical safety pictogram.


- Multiple colour combinations available.
- Possibility of matching the brand and corporate design.
- Possibility of combining specific accessories.
- Several types of reflective stripes can be applied on the garment (yellow prismatic, orange prismatic, grey prismatic, grey classic).

Protection against risks of dirt and detrimental actions of slight damage.

The product is designed and manufactured to comply with the requirements of Directive 89/686/EEC.

It is classified as PPE Cat. I.



|                                  |   |  |
|----------------------------------|---|--|
| Category<br><br><b>I</b>         | Colours<br>01 White, 28 Yellow, 65 Ochre, 12 Orange, 10 Red, 11 Plum, 08 Khaki, 47 Dark Olive Green, 07 Green, 06 Dark Green, 05 Royal Blue, 21 Turquoise, 04 Blue, 18 Navy Blue, 29 Pearl, 14 Turtledove, 42 Lead, 03 Mousey Grey, 41 Charcoal Grey, 02 Black. | Available Sizes<br>38-66   |
| Quantity/Carton<br><br><b>50</b> | Important Information<br>Keep in a cool dry place, far from heat sources and direct light.<br>Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.                 | Recommended for<br>Metalworking industry, Construction, Logistics, Transport, Agriculture, Maintenance.  |
| Dexterity                        | EC Standards<br>EN ISO 13688  | Storage and cleaning<br>We recommend to follow the washing instructions.<br> |