

Sir Safety System S.p.A. Single-member company
Wholly-owned subsidiary of Sir Holding Srl
Via dei Fornaciai, 9 - Santa Maria degli Angeli
06081 Assisi - Perugia - Italy
Tel.+39 075.8043737 (R.A.) - Fax +39 075.8048686

VAT Nr. IT 03359340548
Viale Europa 74
20090 Cusago Milano
Tel. +39 02.90394575 (R.A.)
Fax +39 02.90394441

export@sirsafety.com
www.sirsafety.com

COMPANY WITH
QUALITY SYSTEM
CERTIFIED BY DNV GL
= ISO 9001 =



Name: Light Carboflame Coverall	Code: 35282R	Light Carboflame and Carboflame
--	---------------------	--

Description

Coverall with shirt collar in 99% cotton, 1% carbon fibre, 230 g/m². two-way central zipper closure with flap and Velcro, chest pockets with zipper and flaps with Velcro, loop for gas detector above right pocket; pocket on left sleeve with flap and Velcro, frontal slanted pockets with flaps and Velcro, hidden exterior-to-interior access, elastic waistband. Two back pockets with flaps and Velcro, knee pad pockets with Velcro closure; ruler pocket with flap and Velcro, reflective band on the shoulders, legs and arms, triple stitching.

- The Light Carboflame Coverall guarantees a high level of protection while maintaining lightness and breathability of the fabric.
- It is suitable for welding processes.
- Ensures great comfort, thanks to the percentage of cotton used.
- Night safety due to the reflective bands.

In combination with the coverall, is it possible to wear our under garments: Carboflame undershirt art. 35285 and Carboflame underpants art. 35286, meeting the point A.2 of IEC 61482-2 which is stating that the electric arc protective clothing shall be used with under garments made of materials that would not melt with the arc.





The product is designed and manufactured according to the Directive 89/686/EEC.

It is classified as PPE Cat.II.



Category II	Colours Red	Available Sizes XS-3XL
-----------------------	----------------	---------------------------

Quantity/Carton 500	Important Information Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.	Recommended for Petrochemical Industry, Oil & Gas Industries, Mining Industry.
-------------------------------	---	---

Dexterity	<p>EC Standards</p> <p>EN 1149 CE</p>  <p>EN 11611 CE Class:1;A1</p>  <p>EN 11612 CE</p>  <p>Limited Flame Spread:A1 Convective Heat:B1 Radiant Heat:C1 Contact Heat:F1</p>	<p>Storage and cleaning</p> <p>We recommend to follow the washing instructions.</p> 
-----------	--	--