

Sir Safety System S.p.A. Single-member company Wholly-owned subsidiary of Sir Holding Srl Via dei Fornaciai, 9 - Santa Maria degli Angeli 06081 Assisi - Perugia - Italy Tel.+39 075.8043737 (R.A.) - Fax +39 075.8048686 VAT Nr. IT 03359340548 Viale Europa 74 20090 Cusago Milano Tel. +39 02.90394575 (R.A.) Fax +39 02.90394441

export@sirsafety.com d www.sirsafety.com CEI

COMPANY WITH QUALITY SYSTEM CERTIFIED BY DNV GL = ISO 9001 =



Code: 35306 **Polytech New Generation** Name: Polytech Plus Bib-Trousers Description Bib-trousers made with a double- layer, multipurpose protection, coupled fabric. Outer fabric: 65% Lenzing FR®, 22% aramidic fibre, 12% poyamide, 1% antistatic fibre, weight 250 g/m<sup>2</sup>; Inner fabric: 64% Lenzing FR®, 35% aramidic fibre, 1% antistatic fibre, weight 145 g/m<sup>2</sup>. It features a front zipper closure, two pockets and pen holder with flap and Velcro; two welt pockets, a rear pocket with flap and Velcro, and a ruler pocket; it features utility pockets on the legs, with flap and Velcro closures. Wear and tear reinforcement on the knees. Reflective stripe around the leg. - Polytech Plus Series is made with a multi-purpose fabric that combines antistatic properties with resistance to flames, heat and chemical products. - The inherently flame resistant fabric offers permanent protection. resistant to worn away or washed out. High mechanical resistance, softness and breathability. - Class 2 Arc Flash protection. The bib-trousers shall be worn in combination with the jacket. In combination with the bib-trousers it is possible to wear our under garments: Carboflame undershirt art. 35285 and Carboflame underpants art. 35286, meeting the point A.2 of IEC 61482-2 which is stating that the electric arc protective clothing shall be used with under garments made of materials that would not melt with the arc.

The product is designed and manufactured to comply with the requirements of Directive 89/686/EEC. It is classified as PPE Cat. III.

## Colours Available Sizes Category Ш Navy - Royal Blue 44-62 Quantity/Carton Important Information Recommended for Keep in a cool dry place, far from heat sources Petrochemical Industry, Refining Industry, Chemical Industry, Gas, Water and Electricity and direct light. Make sure the garment is in good condition, Mains Maintenance and Management, Oil & Gas 50 undamaged and clean before use. Once you industry. become aware of a damage, you should immediately replace it. Dexterity EC Standards Storage and cleaning



