

**Sir Safety System S.p.A. Single-member company**  
Wholly-owned subsidiary of Sir Holding Srl  
Via dei Fornaciai, 9 - Santa Maria degli Angeli  
06081 Assisi - Perugia - Italy  
Tel.+39 075.8043737 (R.A.) - Fax +39 075.8048686

VAT Nr. IT 03359340548  
Viale Europa 74  
20090 Cusago Milano  
Tel. +39 02.90394575 (R.A.)  
Fax +39 02.90394441

**export@sirsafety.com**  
**www.sirsafety.com**

COMPANY WITH  
QUALITY SYSTEM  
CERTIFIED BY DNV GL  
= ISO 9001 =



<b>Name: V-Guard Helmet</b>	<b>Code: 38304</b>	<b>Head Protection - MSA</b>
-----------------------------	--------------------	------------------------------

### Description

Helmet made of UV stabilised high density polyethylene (HDPE), with Staz-On 4-point head harness and textile straps with ratchet wheel adjustment, for increased stability. Incorporated slots for hearing and face protection.

Weight: 350 g.

Approved EN 397 standard and responding to optional requirements:

- Very low temperature (-30°C)
- Electrical insulation (440V AC)
- Electrical insulation approval: EN 50365 electric shock up to 1000 V AC or 1500 V DC
- Antistatic approval: EN 13463-1 for the zone 1,2,21 and 22, Group IIA

The product is designed and manufactured to comply with the essential health and safety requirements of Directive 89/686/EEC, and to conform to the requirements of EN 397, EN 50365, EN 13463. It is classified as PPE Cat. III.



<b>Category</b> <b>III</b>	<b>Colours</b> Yellow	<b>Available Sizes</b> 52-62
<b>Quantity/Carton</b> <b>20</b>	<b>Important Information</b> Make sure the helmet is in good condition before use and its shell is not damaged: inspect for cracking, abrasions, change of colouring or dents. Once you become aware of a damage, you should immediately replace it.	<b>Recommended for</b> Safety helmet suitable to protect the worker's head from objects falling from a height or accidental impacts in industrial plants.
<b>Dexterity</b>	<b>EC Standards</b> EN 397 CE  EN 13463-1 CE Values: 1, 2, 21, 22 Group: IIA  EN 50365	<b>Storage and cleaning</b> Keep in a cool dry place, far from heat sources and direct light. Clean using only a neutral detergent and warm water. Do not use any solvents.