

**Sir Safety System S.p.A. Single-member company**  
Wholly-owned subsidiary of Sir Holding Srl  
Via dei Fornaciai, 9 - Santa Maria degli Angeli  
06081 Assisi - Perugia - Italy  
Tel.+39 075.8043737 (R.A.) - Fax +39 075.8048686

VAT Nr. IT 03359340548  
Viale Europa 74  
20090 Cusago Milano  
Tel. +39 02.90394575 (R.A.)  
Fax +39 02.90394441

export@sirsafety.com  
www.sirsafety.com

COMPANY WITH  
QUALITY SYSTEM  
CERTIFIED BY DNV GL  
= ISO 9001 =



<b>Name: Chemfor-T Coverall</b>	<b>Code: 30237T</b>	<b>Chemical Protection Type 4 - 5 - 6</b>
---------------------------------	---------------------	---



### Description

Coverall with antistatic properties, in polypropylene coated with a high-tenacity breathable microporous film; the specific material guarantees resistance against liquid splashes, including inorganic liquids, and dusts up to 0.6 micron. It features a zipper closure with flap and elastic hood, cuffs, waistband and ankles.

- High protection, resistant and breathable.
- Resistant to splashes, including inorganic liquids and dusts up to 0.6 micron
- Antistatic treatment.
- Hygienic, because it does not lose fibres.

The product is designed and manufactured according to the provisions of Council Directive 89/686/EEC, with harmonized standards EN 13982 TYPE 5, EN 13034 TYPE 6 and EN 1149. It is classified as PPE Cat. III.



Category <b>III</b>	Colours White	Available Sizes M-XXL
Quantity/Carton <b>25</b>	Important Information Keep in a cool dry place, far from heat sources and direct light. Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.	Recommended for Cleaning, Construction, Industrial plants installation and maintenance, Waste and asbestos collection and disposal, Painting, Chemical and testing laboratories, Agribusiness industry, Shipbuilding, Reclamation and pest control.
Dexterity	EC Standards EN 1149 CE  EN 13034 CE  Type:6 EN ISO 13982 CE Type:5	Storage and cleaning Keep in a cool dry place, far from heat sources and direct light. Disposable equipment: no further inspection is necessary. 