

**Sir Safety System S.p.A. Single-member company**  
Wholly-owned subsidiary of Sir Holding Srl  
Via dei Fornaciai, 9 - Santa Maria degli Angeli  
06081 Assisi - Perugia - Italy  
Tel.+39 075.8043737 (R.A.) - Fax +39 075.8048686

VAT Nr. IT 03359340548  
Viale Europa 74  
20090 Cusago Milano  
Tel. +39 02.90394575 (R.A.)  
Fax +39 02.90394441

export@sirsafety.com  
www.sirsafety.com

COMPANY WITH  
QUALITY SYSTEM  
CERTIFIED BY DNV GL  
= ISO 9001 =



|                               |                    |                         |
|-------------------------------|--------------------|-------------------------|
| <b>Name: Evolution Jacket</b> | <b>Code: 30603</b> | <b>Evolution Series</b> |
|-------------------------------|--------------------|-------------------------|

### Description


Jacket made of Evolution fabric, 65% polyester and 35% cotton, weight 240 g/m<sup>2</sup>. Four button closure, two side pockets, small chest pocket, jointed double seams and reinforcement runners in contrasting colour. Mechanical safety pictogram.

- Enhanced mechanical strength.
- Fabric resistant to dirt and chemicals
- Wide range of colours available.
- Bright colours resistant to repeated washings.
- Bespoke options with over 80 different accessories and possibility to apply 4 types of reflective stripes (yellow prismatic, orange prismatic, grey prismatic, grey classic).

Protection against risks of dirt and detrimental actions of slight damage.

The product is designed and manufactured to comply with the requirements of Directive 89/686/EEC.  
It is classified as PPE Cat. I.



|                                  |   |  |
|----------------------------------|---|--|
| Category<br><br><b>I</b>         | Colours<br>01 White, 28 Yellow, 65 Ochre, 12 Orange, 10 Red, 11 Plum, 08 Khaki, 47 Dark Olive Green, 07 Green, 06 Dark Green, 05 Royal Blue, 21 Turquoise, 04 Blue, 18 Navy Blue, 29 Pearl, 14 Turtledove, 42 Lead, 03 Mousey Grey, 41 Charcoal Grey, 02 Black. | Available Sizes<br>38-66   |
| Quantity/Carton<br><br><b>50</b> | Important Information<br>Keep in a cool dry place, far from heat sources and direct light.<br>Make sure the garment is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.                 | Recommended for<br>Manufacturing, Construction, Cleaning, Maintenance, Petrol stations, Mechanical Industry.   |
| Dexterity                        | EC Standards<br>EN ISO 13688  | Storage and cleaning<br>We recommend to follow the washing instructions.<br> |